

Summary of Comments - Biggest Single Improvement

Name	Practicality and Function	Heating and Comfort	Decor
Chapel Member			
Chapel Member	Glass doors into chapel. Chapel seating		
Chapel Member			
Chapel Member	Altering lower porch Overhaul of chapel		
Chapel Member	Folding doors on stage or new curtain		
Chapel Member	Thermal efficiency		
Chapel Member	Freshen the outside signage, doors. Lose the blue paint!		
Chapel Member	Velux window over stage		
Chapel Member	Handrails for all steps & some access improvements. Bright signboard with accurate info.		
Chapel Member			
Chapel Member	Ramp second aisle into chapel		
Chapel Member			
Chapel Member	Upgrading access to Lower Hall from street, including enlarging lower porch and eliminating the steps.		
Chapel Member	Could the land above chapel be purchased and opened out either for future development. Provide a way people could see into the building - have an accessible and visible coffee area off Church Street		
Chapel Member	Improve the entrance to Sunday school making it more welcoming and disabled friendly		
Chapel Member	A better heating system which is simpler to operate.		
Chapel Member	Handrails. Heating controls. Decorate Sunday school		
Hirer			
Hirer	Sort out the levels		
Hirer	Entrance to lower hall ! Lower porch is too small- can't fit people in and unable to see the parents and who is collecting the children. Steep stone steps don't help.		

Summary of Comments - Biggest Single Improvement

Hirer	nc		