

Summary of Comments - Bible Class – Coffee Room

| Name | Practicality and Function | Heating and Comfort | Decor |
|---------------|--|---|---|
| Chapel Member | Accessed by steps again | Noisy heaters – unpleasant to sit near them. Heaters irritate my eyes. | |
| Chapel Member | NC | | |
| Chapel Member | OK | Heating poor | |
| Chapel Member | The concertina doors are never used and take up space and the track is a potential hazard to tripping or heels! It's a same there are so many steps for people to have to go up to get to it. It makes it very unfriendly to a disabled person. Also not having a toilet near where we serve drinks isn't great for the less able bodied. Generally is a nice, welcoming room, it's a shame only chapel people see it. As an 'overspill' to chapel, it's unwelcoming and impractical. You can't see anything and you wouldn't feel part of the service. The doorways between it and chapel are narrow. | Heating is erratic, often too hot or too cold. The heaters are also noisy, so make it hard to hear what people are saying when they are on. The heat distribution isn't very good either. | Is a bit tatty, but not dreadful. People don't walk in and think it looks bad, its only if you inspect the paintwork that you see scuffs |
| Chapel Member | NC | | |
| Chapel Member | Work well as "Community Rooms" | Insulation of walls and loft space essential. | |
| Chapel Member | NC | | |
| Chapel Member | The best room in the building. Changing the external doors has opened it up. | Add this room to the CH circuit and remove the gas heaters. | Keep it tidy. |
| Chapel Member | | Can't avoid the hot air from heaters in winter. Heating is responsive. | |
| Chapel Member | Install "Dumb Waiter" from Den | | |
| Chapel Member | Install "Dumb Waiter" from kitchen to save carrying trays upstairs | | |
| Chapel Member | Works well especially with new porch area. | | Redecorate when needed and re-stain doors |
| Chapel Member | Now regularly used after services. Could we have more permanent drink serving facilities with coffee machine, kettle etc? Improved access from Chapel needed for the mobility impaired. | Reasonable | Refresh |

Summary of Comments - Bible Class – Coffee Room

| | | | |
|---------------|---|---|--|
| Chapel Member | Some form of kitchen / toilet facilities would be appreciated on this level. | | |
| Chapel Member | Nice Room. | Add this room to the CH circuit and remove the gas heaters | |
| Chapel Member | The air ventilation grate in the gable wall needs a bird mesh put in over the winter before nesting time as we have jackdaws breeding in the ceiling void! Another job we can do ourselves. | As with the SS room (lower hall), I think we should consider insulating the roof space for exactly the same reasons. It's low cost and can be done by ourselves. | |
| Chapel Member | | Heating is not very effective, is noisy and tends to make people uncomfortable (either too hot or freezing). Thermostat not always a help. A simpler to operate system would be good, and one which provides more of a background, consistent heat rather than erratic, noisy blasts! | |
| Hirer | NC | | |
| Hirer | Don't use except to access our store cupboard | | |
| Hirer | NC | | |

505 words